

Plugin/Software	CuttingMaster 2		CuttingMaster 3		CuttingMaster 4		Graphtec Studio		Graphtec Pro Studio		Graphtec Pro Studio Plus	
OS	Windows	Mac	Windows	Mac	Windows	Mac	Windows	Mac	Windows	Mac	Windows	Mac
Versionen	7, 8, 8.1 (32&64)	10.4 - 10.10	7, 8, 8.1, 10 (32&64)	10.5 - 10.12	7, 8, 8.1, 10 (32&64)	OS X 10.7, 10.8, Illustrator 5 (Ver. 2.82), OS X 10.9 - 10.11, OS X 10.12 - 10.15 (Ver. 3.30)	XP(SP3), Vista, 7, 8	OS X10.5 (Ver. 2.1.200), OS X10.6 - 10.9 (Ver. 2.2.1279), OS X 10.10 - 10.11, OS X 10.12 - 10.15 (Ver. 3.0.032)	7, 8, 8.1, 10 (32&64)	nicht verfügbar	7, 8, 8.1, 10 (32&64)	nicht verfügbar
Illustrator	8, 9, 10, CS2, CS3, CS4, CS5, CS6, CC, CC2014	10, CS2, CS3, CS4, CS5, CS6, CC, CC2014	CS4, CS5, CS6, CC	CS4, CS5, CS6, CC	CS5, CS6, CC2018, CC2019, CC2020	CS5, CS6, CC2018, CC2019, CC2020						
CorelDraw	10, 11, 12, X3, X4, X5, X6, X7	nicht verfügbar	X4, X5, X6	nicht verfügbar	X4, X5, X6, X7, X8	nicht verfügbar						
Modell												
FC9000					X	X	X		X		X	
FC8600	X	X	X	X	X	X	X	X	X	X	X	X
FC8000	X	X	X	X	X	X	X	X	X	X	X	X
FC7000 MKII												
FC7000	X	X										
FC5100	X	X										
CE7000					X	X	X		X		X	
CE LITE-50					X	X			X		X	
CE6000 Plus				X	X	X		X	X		X	
CE6000	X	X	X	X	X	X	X	X	X	X	X	X
CE5000	X	X	X *1	X *1	X	X	X *1	X *1	X	X	X	X
CE3000 MKII	X	X										
CE3000	X	X										

*1 Plotter benötigt Firmware 3.90 oder > rsp. 6.20 oder > (Neues Main Board)

Stand: 9.12.2019

Quelle: Graphtec